National Transportation Safety Board NTSB ID: DEN03LA022 Aircraft Registration Number: N4746T FACTUAL REPORT Occurrence Date: 11/26/2002 Most Critical Injury: None Occurrence Type: Accident Investigated By: NTSB ETYBO Location/Time Nearest City/Place State Zip Code Local Time Time Zone CO 81130 1430 **MST** Creede Distance From Landing Facility: 70 Direction From Airport: 1 Airport Proximity: On Airport Aircraft Information Summary Aircraft Manufacturer Model/Series Type of Aircraft

Sightseeing Flight: No

Air Medical Transport Flight: No

Narrative

Maule

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On November 26, 2002, at 1430 mountain standard time, a Maule M-4-210, N4746T, piloted by a private pilot, was substantially damaged when the airplane departed the right side of runway 25 (6,880 feet by 60 feet, dry asphalt) and impacted into a gully at the Creede-Mineral County Memorial Airport, Creede, Colorado. Visual meteorological conditions prevailed at the time of the accident. The personal flight was being conducted under the provisions of Title 14 CFR Part 91 without a flight plan. The pilot reported no injuries The flight originated at Alamosa, Colorado, at 1315, and was en route to Creede, Colorado.

M-4-210

The pilot reported that during landing, he encountered an unexpected crosswind, and the airplane drifted off of the runway.

An examination of the airplane showed the right main landing gear broken aft. The outboard portions of the left and right wings near the tips were broken and torn. The left wing strut was bent aft. The propeller showed chordwise scratches. Flight control continuity was confirmed. An examination of the engine and other airplane systems revealed no anomalies.

At 1452, the weather conditions at Alamosa, Colorado (56 miles from Creede at 104 degrees), were reported as clear skies, 10 miles visibility, and winds of 040 degrees at 6 knots.

Federal Aviation Administration records showed the pilot obtained his private pilot certificate on September 14, 2002. The pilot reported that at the time of the accident, he had 87 total flying hours, and 32 hours in the accident airplane, 7 of which were as pilot-in-command.

Airplane

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: DEN03LA022

Occurrence Date: 11/26/2002

| AVIATION Occu | | | rence Type | : Accident | | | | | | | | | |
|---|--------------------|-------------------------------------|----------------------------|--|----------|-------------------------|----------|---------------------|---------------------|-----------|-----------------|-----------|--|
| Landing Facility/Approach In | formation | • | | | | | | | | | | | |
| Airport Name | Airport ID: | Airport Eleva | rt Elevation Runway Used F | | | Runwa | ay Lengt | h | Runw | vay Width | | | |
| Creede-Mineral County Memorial Q39 | | | | 8680 F | t. MSL | . 25 | | 6880 | 80 | | 60 | | |
| Runway Surface Type: Asphalt | | | | | | | | | | | | | |
| Runway Surface Condition: Dry | | | | | | | | | | | | | |
| Type Instrument Approach: NONE | E | | | | | | | | | | | | |
| VFR Approach/Landing: Full Stop | ; Traffic Pattern | | | | | | | | | | | | |
| Aircraft Information | | | | | | | | | | | | | |
| Aircraft Manufacturer Maule | | | Model | /Series 210 | | | | | Serial 1009 | Number | | | |
| Airworthiness Certificate(s): Normal | | | | | | | | | | | | | |
| Landing Gear Type: Tailwheel | | | | | | | | | | | | | |
| Homebuilt Aircraft? No | | | | | | Certified Max Gross Wt. | | | | | r of Engines: 1 | | |
| Engine Type: | | | | Engine Manufacturer: Model/Series: IO-360A | | | | | Rated Pow 210 HP | | | | |
| - Aircraft Inspection Information | | | | | | | • | | | • | | | |
| Type of Last Inspection Da | | | | Date of Last Inspection Time Since | | | | nce Last Inspection | | | | tal Time | |
| Annual 02 | | | | 02/2002 48 F | | | | | ours | | 2 | 970 Hours | |
| - Emergency Locator Transmitter (| ELT) Information | | | | | | | | | | | | |
| ELT Installed? Yes ELT Operated? No ELT Aided in Locating Accident Site? No | | | | | | | | | | | | | |
| Owner/Operator Information | | | | | | | | | | | | | |
| Registered Aircraft Owner | Street | Street Address 415 Starlight Circle | | | | | | | | | | | |
| Buck Stroh | | | | City | | | | | | | | Zip Code | |
| | Street A | Creede CO 81130 Street Address | | | | | | | | | | | |
| Operator of Aircraft | | | | | | | | | | | | | |
| Same as Reg'd Aircraft Owner | | | | City | | | | | | | 9 | Zip Code | |
| Operator Does Business As: Operator Designator Code: | | | | | | | | | | | | | |
| - Type of U.S. Certificate(s) Held: 1 | None | | | | | | | | | | | | |
| Air Carrier Operating Certificate(s) | : | | | | | | | | | | | | |
| Operating Certificate: | | | | Operator | Certific | cate: | | | | | | | |
| Regulation Flight Conducted Unde | r: Part 91: Genera | ıl Aviati | on | • | | | | | | | | | |
| Type of Flight Operation Conducted | d: Personal | | | | | | | | | | | | |
| |] | FACTU | JAL REPO | RT - AVIAT | ION | | | | | | | Page 2 | |

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: DEN03LA022

Occurrence Date: 11/26/2002

| AVIATI | Occurrence Type: Accident | | | | | | | | | | | | |
|--|--------------------------------------|------------------------|---------------------------|-------------------------|-----------|--------|--------------------------------------|--------------------|------------|------------|----------------|------------|---------------------|
| First Pilot Information | | | | | | | | | | | | | |
| Name | City | | | | | State | Da | te of Birth | Age | | | | |
| On File On Fi | | | | | | | | le | | | | n File | 49 |
| Sex: M Seat Occupied | Certificate Number: On File | | | | | | | | | | | | |
| Certificate(s): Private | | | | | | | | | | | | | |
| Airplane Rating(s): Single-engine Land | | | | | | | | | | | | | |
| Rotorcraft/Glider/LTA: None | | | | | | | | | | | | | |
| Instrument Rating(s): None | | | | | | | | | | | | | |
| Instructor Rating(s): None | | | | | | | | | | | | | |
| Type Rating/Endorsement for | or Accident/In | cident Aircra | ft? No | | | С | urrent E | Biennial | Flight Re | view? | 09/200 | 2 | |
| Medical Cert.: Class 3 | Medica | al Cert. Status | s: Valid Me | dicalno w | aivers/li | im. | | Da | ate of Las | t Medi | cal Exar | m: 07/2002 | |
| | | | | | | | | | | | | | |
| - Flight Time Matrix | | This Make and Model | Airplane Single Engine | Airplane Mult-Engine | Nigh | nt | Actual | Instrument | Simulated | Rotorcraft | | Glider | Lighter Than Air |
| Total Time 87 | | 32 | 87 | | | 4 | | | | | | | |
| Pilot In Command(PIC) | 45 | 7 | 45 | | - | | | | | + | | | |
| Instructor | 50 | 04 | | | + | | | | | + | | | |
| Last 90 Days Last 30 Days | 53 19 | 21 19 | 53 19 | | | | | | | | | | |
| Last 30 Days 19 19 19 Last 24 Hours | | | | | | | | | | + | | | |
| Seatbelt Used? Yes | Shou | lder Harness | Used? Yes | | · | Toxico | ology Performed? No Second Pilot? No | | | | | | |
| | <u> </u> | | | | | | | | | | <u> </u> | | |
| Flight Plan/Itinerary | | | | | | | | | | | | | |
| Type of Flight Plan Filed: N | one | | | | | | | | | | | | |
| Departure Point | | | | <u> </u> | | State | : | Airport Identifier | | | Departure Time | | Time Zone |
| Alamosa | | СО | | ALS | | 1 | 1315 | | MST | | | | |
| Destination | Destination State Airport Identifier | | | | | | | | | | | | |
| Same as Accident/Incident Location Q39 | | | | | | | | | | | | | |
| Type of Clearance: None | | | | | | | | | | | | | |
| Type of Airspace: Class E | | | | | | | | | | | | | |
| Weather Information | | | | | | | | | | | | | |
| Source of Briefing: No record of briefing | | | | | | | | | | | | | |
| Method of Briefing: Unknown | | | | | | | | | | | | | |
| FACTUAL REPORT - AVIATION Page 3 | | | | | | | | | | | | | |

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: DEN03LA022

Occurrence Date: 11/26/2002

Occurrence Type: Accident

| | ETYBORY | Occurrenc | Occurrence Type: Accident | | | | | | | | | | |
|---|-------------------------------------|-----------|---|--------|---------------------------------|-------|-------------|--------------|-------|------------------------------|-----|--|--|
| Weather Information | | | | | | | | | | | | | |
| WOF ID | Observation Time | Time Zone | WOF Elevati | ion | WOF Distance From Accident Site | | | | | Direction From Accident Site | | | |
| ALS | 1452 | MST | 8680 Ft. | . MSL | 1 NM | | | | | 250 Deg. Mag. | | | |
| Sky/Lowes | st Cloud Condition: Cle | | | | Ft. | AGL | Condition o | f Light: Day | | | | | |
| Lowest Ce | Ft. | AGL | Visib | ility: | 10 | 10 SM | | meter: | 30.18 | "Hg | | | |
| Temperatu | ure: 3 °C | -12 °C | Wind Direction: 40 Density Altitude: 9057 | | | | | | | | Ft. | | |
| Wind Spee | ed: 6 | | Weather Condtions at Accident Site: Visual Conditions | | | | | | | | | | |
| Visibility (RVR): Ft. Visibility (RVV) | | | .VV) | SM | Intensity of Precipitation: | | | | | | | | |
| Restriction | ns to Visibility: None | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| Type of Pro | Type of Precipitation: None | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| Accident Information | | | | | | | | | | | | | |
| Aircraft Damage: Substantial Aircraft F | | | | | Aircraft Exp | | | | | xplosion None | | | |
| Classificati | ion: U.S. Registered/l | U.S. Soil | | | | | | | | | | | |
| - Injury Su | - Injury Summary Matrix Fatal Serio | | | or | None TOTAL | | | | | | | | |
| First Pi | ilot | | | | 1 | | 1 | | | | | | |
| Second | d Pilot | | | | | | 7 | | | | | | |
| Studen | nt Pilot | | | | | | | | | | | | |
| Flight I | Instructor | | | | | | ┨ | | | | | | |
| Check | Pilot | | | | | | 7 | | | | | | |
| Flight E | Engineer | | | | | | | | | | | | |
| Cabin / | Attendants | | | | | | | | | | | | |
| Other 0 | | | | | | | 7 | | | | | | |
| Passer | ngers | | | | | | | | | | | | |
| - TOTAL A | ABOARD - | | | | 1 | | 1 | | | | | | |
| Other (| | 1 | | | | | \dashv | | | | | | |
| - GRAND | - GRAND TOTAL - 1 1 | | | | | | | | | | | | |
| | | | | | | | • | | | | | | |

National Transportation Safety Board

FACTUAL REPORT AVIATION NTSB ID: DEN03LA022

Occurrence Date: 11/26/2002

Occurrence Type: Accident

| A I ' ' ' ' | |
|-----------------|----------------|
| Administrative | Intormation |
| Autililionalive | IIIIOIIIIauoii |

Investigator-In-Charge (IIC)

David C. Bowling

Additional Persons Participating in This Accident/Incident Investigation:

John Botterill Air Safety Inspector Federal Aviation Administration Denver, CO 80249